



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 10
1200 Sixth Avenue, Suite 900
Seattle, WA 98101-3140

IDD 6888

S F

8/13/12

AUG 13 2012

OFFICE OF
COMPLIANCE AND ENFORCEMENT

Reply to: OCE-127

Certified Mail Number 7011 2970 0000 0876 4446
Return Receipt Requested

James Cagle, Risk Manager - EHS
Nu-West Industries, Inc.
Agrium Conda Phosphate Operations
3010 Conda Road
Soda Springs, Idaho 83276

Re: EPA Inspection Photographs

Dear Mr. Cagle:

During the EPA inspection of your facility last week, you had requested copies of the photographs that I took. The enclosed CD contains those photographs. Please note that the time recorded on each photograph reflects the camera setting, which was Pacific Daylight Time.

If you have any questions, feel free to call me at (206) 553-2964. Alternatively, you may reach me via email at Magolske.Peter@epamail.epa.gov. Thank you.

Sincerely,

Peter Magolske
Air / RCRA Compliance Unit

cc: Brian Monson, Idaho Department of Environmental Quality

enclosure

FILE COPY